



MEYLE[®]
Products

MEYLE br. Referentni br.

Selen blok mosta: 36-14 710 0000/HD* 55400EQ700

Pribor za popravku: 36-14 710 0001/HD 55400EQ700

*"Part of" - MEYLE part
is only a component of
the OE reference

Selen blok mosta (zadnje osovine)

odgovara za

Nissan X-Trail T 30



kao OE



Problem

- Prekomjerno deformisanje dijela od gume do metala uslijed povećanih dinamičkih sila.
- Selen blok nije dostupan zasebno do sada.

Posljedica

- Skupa zamjena cjelokupno pod okvira
- Velika buka i smanjena bezbjednost u vožnji prilikom kočenja.



Rješenje



- Pojačanje dijela od gume do metala redizajnom unutrašnjeg prstena.
- Sporni dio je ojačan sa više gume.

Prednost

- Značajna ušteda na trošku materijala.
- Duži vijek trajanja zajedno sa sigurnošću i udobnošću u vožnji.

kao OE



MEYLE-HD-verzija

